

OREGON CORNER RESTORATION FORM

Section 14 Township 20 South, Range 8 West
County Douglas Date 1 March 2013

FILED
Date: 3/29/2013 By: JC
This survey consists of:
Map: _____
Narrative: _____
Corner Rpt: CS 65/78-17

DOUGLAS COUNTY
SURVEYOR

Corner Description

1/4 Corner
Sections 11,14

- Condition Report Only
- Not Found
- Renewed
- Unrecorded
- Surveyed In
- Referenced Out

Previous Renewals / Surveys, etc.

Monument (s) & Accessories Found: (Condition and Source)

Found 1954 GLO brass cap with the following accessories:

- 15" D. Fir snag bears S 57° W 35.0 ft. – healed face
- 17" D. Fir snag bears N 45° W 12.0 ft. – healed face
- Record 12" D. Fir snag N34° E 17.5 ft. - not found
- 20" D. Fir snag bears N 34° E 17.5 ft. – healed face
- 10" D. Fir bears S 2° W 23.3 ft. – healed face
- 17" D. Fir bears N 73° W 22.0 ft. – healed face

Monument Detail

Sketch

Monument Set (Procedures and Description)

None

New Accessories

- 14" D. Fir bears N 19° W 29.5 ft. - blazed, scribed, 1/4 S11 BT
- 14" D. Fir bears S 57° W 10.1 ft. - blazed, scribed, 1/4 S14 BT

Location & Comments

Corner has steel post _____ Compass Declination 16° East
adjacent to it. _____ Firm/Agency Northwest Land
All BT's have red painted _____ Surveying Inc.
bands and yellow tags. _____ Address P.O. Box 2827
 _____ Florence, OR 97439
 _____ Party Chief Ron Rice
 _____ Notes _____
 _____ Witness _____

Surveyor's Seal



RENEWS: 12-31-2014

C.S. FILE 65/78-17

540550