

FILED

Date: 3/29/2013 By: X

This survey consists of:

Map: _____

Narrative: _____

Corner Rpt: CS 65/78-18

DOUGLAS COUNTY
SURVEYOR

OREGON CORNER RESTORATION FORM

Section 14 Township 20 South, Range 8 West
County Douglas Date 1 March 2013

Corner Description

Section Corner
Sections 13,14,23,24

- Condition Report Only
- Not Found
- Renewed
- Unrecorded
- Surveyed In
- Referenced Out

Previous Renewals / Surveys, etc.

Monument (s) & Accessories Found: (Condition and Source)

Found 1954 GLO brass cap with the following accessories:

A burned fir stump, 27" dia., bears N.52½° E., 53.5 ft., with a healed blaze.
(Found same)

A maple clump growing around a root hole, bears N.27°W., 22.4 ft., no marks visible.
(Found same)

A fir, 17" dia., bears N.13½° E., 33.7 ft., mkd. T20S R8W S13 BT.
(Found 21", healed face)

A fir, 11" dia., bears S.32° E., 38.8 ft., mkd. T20S R8W S24 BT.
(Found 14", healed face)

A fir, 14" dia., bears S.60½° W., 56.4 ft., mkd. T20S R8W S23 BT.
(Found 16", healed face)

A fir, 10" dia., bears N.86½° W., 46.5 ft., mkd. T20S R8W S14 BT.
(Found 10", healed face)

Monument Detail

Sketch

Monument Set (Procedures and Description)

None

New Accessories

None

Location & Comments

Corner has steel post _____ Compass Declination 16° East

adjacent to it. _____ Firm/Agency Northwest Land

All BT's have red painted _____ Surveying Inc.

bands and yellow tags. _____ Address P.O. Box 2827
_____ Florence, OR 97439

_____ Party Chief Ron Rice

_____ Notes _____

_____ Witness _____

Surveyor's Seal



RENEWS: 12-31-2014

C.S. FILE 65/78-18

65-78-18