

OREGON CORNER RESTORATION FORM

Section 14 Township 20 South, Range 8 West  
County Douglas Date 1 March 2013

FILED  
Date: 3/29/2013 By: JC  
This survey consists of:  
Map: \_\_\_\_\_  
Narrative: \_\_\_\_\_  
Corner Rpt: CS 65/78-19

DOUGLAS COUNTY  
SURVEYOR

Corner Description

1/4 Corner  
Sections 13,14

- Condition Report Only
- Not Found
- Renewed
- Unrecorded
- Surveyed In
- Referenced Out

Previous Renewals / Surveys, etc.

Monument (s) & Accessories Found: (Condition and Source)

Found 1954 GLO brass cap with the following accessories:  
11" D. Fir bears N 40° E 5.5 ft. – healed face  
14" D. Fir bears S 34-1/2° W 13.2 ft. – healed face

Monument Detail

Sketch

Monument Set (Procedures and Description)

None

New Accessories

13" D. Fir bears S 58° E 16.3 ft. - blazed, scribed, 1/4 S13 BT  
11" D. Fir bears S 88° W 16.6 ft. - blazed, scribed, 1/4 S14 BT

Location & Comments

Corner has steel post \_\_\_\_\_ Compass Declination 16° East  
adjacent to it. \_\_\_\_\_ Firm/Agency Northwest Land  
All BT's have red painted \_\_\_\_\_ Surveying Inc.  
bands and yellow tags. \_\_\_\_\_ Address P.O. Box 2827  
\_\_\_\_\_ Florence, OR 97439  
\_\_\_\_\_ Party Chief Ron Rice  
\_\_\_\_\_ Notes \_\_\_\_\_  
\_\_\_\_\_ Witness \_\_\_\_\_

Surveyor's Seal



RENEWS: 12-31-2014

C.S. FILE 65/78-19

6504 0