

OREGON CORNER RESTORATION FORM

Section 14 Township 20 South, Range 8 West
County Douglas Date 1 March 2013

FILED
Date: 3/29/2013 By: JC
This survey consists of:
Map: _____
Narrative: _____
Corner Rpt: CS 65/78-20

DOUGLAS COUNTY
SURVEYOR

Corner Description

Section Corner
Sections 11,12,13,14

- Condition Report Only
- Not Found
- Renewed
- Unrecorded
- Surveyed In
- Referenced Out

Previous Renewals / Surveys, etc.

Monument (s) & Accessories Found: (Condition and Source)

Found 1954 GLO brass cap with the following accessories:
37" D. Fir snag bears S 60° E 31'.0' – burned face, no scribe marks
30" D. Fir snag bears S 18° W 15.8' – no marks
34" D. Fir stump bears N 13-1/2° W 48.2' – burned face, no scribing
35" D. Fir stump bears N 54° E 19.1' – rotted face, cruiser mark in bark

Monument Detail Sketch

Monument Set (Procedures and Description)

None

New Accessories

8" D. Fir bears N 21° W 11.2 ft. - blazed, scribed, T20S R8W S11 BT
14" D. Fir bears N 38° E 24.2 ft. - blazed, scribed, T20S R8W S12 BT
15" D. Fir bears S 1° E 24.6 ft. - blazed, scribed, T20S R8W S13 BT
12" D. Fir bears S 26° W 9.8 ft. - blazed, scribed, T20S R8W S14 BT

Location & Comments

Corner has steel post adjacent to it. Compass Declination 16° East
All BT's have red painted bands and yellow tags. Firm/Agency Northwest Land Surveying Inc.
Address P.O. Box 2827
Florence, OR 97439
Party Chief Ron Rice
Notes
Witness Rob Ward

Surveyor's Seal



RENEWALS: 12-31-2014

C.S. FILE 65/78-20

600200