

FILED

OREGON CORNER RESTORATION FORM

Date: 3-29-2013 By: JC
This survey consists of:
Map: _____
Narrative: _____
Corner Rpt: CS 65/78-21

Section 12 Township 20 South, Range 8 West
County Douglas Date 28 February 2013

DOUGLAS COUNTY
SURVEYOR

Corner Description

E 1/4
Section 12 only

- Condition Report Only
- Not Found
- Renewed
- Unrecorded
- Surveyed In
- Referenced Out

Previous Renewals / Surveys, etc.

Monument (s) & Accessories Found: (Condition and Source)

Found: On 2-28-2013 a 1954 GLO brass cap bent to the West, properly stamped. (Straightened pipe on 2-30-2013)
 16" Fir stump bears S.63° E., 10.2 ft., scar visible, 1884 BT. (Rotted face on 2-28-2013)
 54" Fir stump bears S.52° W., 6.2 ft., no marks, 1954 BT. (Found R. R. spike in top at 6.2 ft. on 2-28-2013)
 44" Fir stump bears N.51° W., 46.4 ft., scribe visible, 1954 BT. (Same condition on 2-28-2013)
 8" Fir bears N.14° W., 10.0 ft., scribed, painted red. (Found 17" D. Fir with healed face on 2-28-2013)
 R.R. spike in top of 54" Fir stump. Stump bears S.3° W., 5.3 ft. from corner. (Not found on 2-28-2013)

Monument Detail

Sketch

Monument Set (Procedures and Description)

None

New Accessories

16" D. Fir bears S 12° E 16.8 ft. blazed, scribed, X BT
 21" D. Fir bears N 66° E 13.0 ft. blazed, scribed, X BT

Location & Comments

Corner has steel post adjacent to it. Compass Declination 16° East
All BT's have red painted bands and yellow tags. Firm/Agency Northwest Land Surveying Inc.
 Address P.O. Box 2827 Florence, OR 97439
 Party Chief Ron Rice
 Notes _____
 Witness _____

Surveyor's Seal



RENEWS: 12-31-2014

C.S. FILE 65/78-21

700540