

OREGON CORNER RESTORATION FORM

Section 12 Township 20 South, Range 8 West
County Douglas Date 28 February 2013

FILED
Date: 3/29/2013 By: JC
This survey consists of:
Map: _____
Narrative: _____
Corner Rpt: CS 65/78-22
DOUGLAS COUNTY
SURVEYOR

Corner Description

Section Corner 1&12 only

- Condition Report Only
- Not Found
- Renewed
- Unrecorded
- Surveyed In
- Referenced Out

Previous Renewals / Surveys, etc.

Monument (s) & Accessories Found: (Condition and Source)

Found: On 2-28-2013 a 1954 GLO brass cap

- 30" Fir stump bears N.50° E., 25.1 ft., no marks.
(Found same on 2-28-2013)
- 52" Fir stump bears N.36½° W., 43.0 ft., scribe visible. (Found same on 2-28-2013)
- 58" Fir snag bears S.87½° W., 24.4 ft., scribe visible. (Found same on 2-28-2013)

Monument Detail

Sketch

Monument Set (Procedures and Description)

None

New Accessories

- 10" D. Fir bears S 11° W 11.8 ft. blazed, scribed, T20S R8W S12 BT
- 19" D. Fir bears N 70° E 14.1 ft. blazed, scribed, T20S R8W S1 BT
- 11" D. Fir bears N 38° W 33.2 ft. blazed, scribed, X BT

Location & Comments

Corner has steel post Compass Declination 16° East
adjacent to it. Firm/Agency Northwest Land
All BT's have red painted Surveying Inc.
bands and yellow tags. Address P.O. Box 2827
_____ Florence, OR 97439
_____ Party Chief Ron Rice
_____ Notes _____
_____ Witness _____

Surveyor's Seal



RENEWS: 12-31-2014

C.S. FILE 65/78-22