

OREGON CORNER RESTORATION FORM

Section 22 Township 20 South, Range 8 West
County Douglas Date 21 March 2013

FILED
Date: 5/6/2013 By: JC
This survey consists of:
Map: _____
Narrative: _____
Corner Rpt: CS 65/78-27

DOUGLAS COUNTY
SURVEYOR

Corner Description

Section Corner
Sections 15,16,21,22

- Condition Report Only
- Not Found
- Renewed
- Unrecorded
- Surveyed In
- Referenced Out

Previous Renewals / Surveys, etc.

Monument (s) & Accessories Found: (Condition and Source)

Found 1950 GLO brass cap with the following accessories:

- A burned cedar stump, 46" dia., bears S.33³/₄° E., 17.2 ft., no marks visible.
(Found same)
- A fir snag, 73" dia., bears S.54° W., 12.5 ft., no marks visible.
(Found same)
- A cedar stump, 51" dia., bears N.30° W., 40.3 ft., with no scribe marks visible on open blaze.
(Found same)
- A decayed cedar stump, size indeterminate, bears N.76°E., 8.3 ft., no marks visible.
(Found same)
- A fir, 11" dia., bears N.48° E., 24.9 ft., mkd. T20S R8W S15 BT.
(Now 15", healed face)
- A fir, 21" dia., bears S.51¹/₄° E., 30.0 ft., mkd. T20S R8W S22 BT.
(Now 26", healed face)
- A fir, 22" dia., bears S.31° W., 54.7 ft., mkd. T20S R8W S21 BT.
(Now 26", healed face)
- A fir, 8" dia., bears N.7³/₄° W., 16.4 ft., mkd. T20S R8WS16 BT
(Now 11", healed face)

Monument Detail

Sketch

Monument Set (Procedures and Description)

None

New Accessories

None

Location & Comments

Corner has steel post _____ Compass Declination 16° East
 adjacent to it. _____ Firm/Agency Northwest Land
All BT's have red painted _____ Surveying Inc.
bands and yellow tags. _____ Address P.O. Box 2827
 _____ Florence, OR 97439
 _____ Party Chief Ron Rice
 _____ Notes _____
 _____ Witness _____

Surveyor's Seal



RENEWS: 12-31-2014

C.S. FILE 65/78-27