

OREGON CORNER RESTORATION FORM

Section 4 Township 20 South, Range 8 West  
County Douglas Date 12 April 2013

FILED  
Date: 5/6/2013 By: JC  
This survey consists of:  
Map: \_\_\_\_\_  
Narrative: \_\_\_\_\_  
Corner Rpt: CS 65/78-28

DOUGLAS COUNTY  
SURVEYOR

Corner Description

1/4 Corner  
Sections 4,33

- Condition Report Only
- Not Found
- Renewed
- Unrecorded
- Surveyed In
- Referenced Out

Previous Renewals / Surveys, etc.

Monument (s) & Accessories Found: (Condition and Source)

Found 1952 GLO brass cap with the following accessories:  
(Record 60" D. Fir N 23° E 87 lks.) – down  
(Record 10" Maple S 26-1/2° E 46 lks.) – missing

Monument Detail

Sketch

Monument Set (Procedures and Description)

None

New Accessories

18" Maple bears N 22° W 22.9 ft. – blazed, scribed 1/4 S33 BT  
17" D. Fir bears N 37° E 28.7 ft. – blazed scribed 1/4 S33 BT  
16" D. Fir bears S 44° E 38.0 ft. – blazed scribed 1/4 S4 BT  
20" D. Fir bears S 63° W 19.8 ft. – blazed scribed 1/4 S4 BT

Location & Comments

Corner has steel post adjacent to it. Compass Declination 16° East  
All BT's have red painted bands and yellow tags. Firm/Agency Northwest Land Surveying Inc.  
 Address P.O. Box 2827  
Florence, OR 97439  
 Party Chief Ron Rice  
 Notes \_\_\_\_\_  
 Witness \_\_\_\_\_

Surveyor's Seal



RENEWALS: 12-31-2014

C.S. FILE 65/78-28