

FILED

Date: 5-6-2013 By: JC

This survey consists of:

Map: _____

Narrative: _____

Corner Rpt: CS 65/78-29

DOUGLAS COUNTY
SURVEYOR

OREGON CORNER RESTORATION FORM

Section 22 Township 20 South, Range 9 West
County Douglas Date 5 April 2013

Corner Description

1/4 Corner
Sections 15,22

- Condition Report Only
- Not Found
- Renewed
- Unrecorded
- Surveyed In
- Referenced Out

Previous Renewals / Surveys, etc.

Monument (s) & Accessories Found: (Condition and Source)

Found 1953 GLO brass cap with the following accessories:

- 55" D. Fir snag bears N 54° W 33.0 ft. – no marks
- 36" D. Fir stump bears S 72-1/2° W 48.2 ft. – no marks
- 42" R. Cedar bears N 30° W 52.8 ft. – healed face

Monument Detail

Sketch

Monument Set (Procedures and Description)

None

New Accessories

- 43" R. Cedar bears N 89° W 11.4 ft. – blazed, scribed 1/4 S15 BT
- 13" Alder bears S 40° E 28.4 ft. – bark scribed 1/4 S22 BT

Location & Comments

Corner has steel post adjacent to it. Compass Declination 16° East
All BT's have red painted bands and yellow tags. Firm/Agency Northwest Land Surveying Inc.
 Address P.O. Box 2827 Florence, OR 97439
 Party Chief Ron Rice
 Notes _____
 Witness _____

Surveyor's Seal



RENEWS: 12-31-2014

C.S. FILE 65/78-29