

FILED

OREGON CORNER RESTORATION FORM

Date: 5-6-2013 By: JC

This survey consists of:

Map: _____

Narrative: _____

Corner Rpt: CS 65/78-31

Section 4 Township 20 South, Range 8 West
County Douglas Date 12 April 2013

DOUGLAS COUNTY
SURVEYOR

Corner Description

Section Corner
Sections 4,5,32,33

- Condition Report Only
- Not Found
- Renewed
- Unrecorded
- Surveyed In
- Referenced Out

Previous Renewals / Surveys, etc.

Monument (s) & Accessories Found: (Condition and Source)

Found 1952 GLO brass cap with the following accessories:

- 34" D.Fir stump bears N 51° E 28.4 ft. – healed face
- 24" D.Fir stump bears S 16-1/2° E 19.1 ft. – healed face
- 24" D.Fir rotted stump bears N 16-1/2° W 31.0 ft. – no marks
- 28" D.Fir snag bears S 6-3/4° W 33.7 ft. – healed face
- D.Fir stump indeterminate diameter bears N 29-3/4° W 31.7 ft. – no marks
- 36" Hem. bears S 9-3/4° E 38.7 ft. – scribing visible (2012 BLM)
- 12" D. Fir bears S 67-1/4° W 16.6 ft. – scribing visible (2012 BLM)
- 12" D. Fir bears N 41° W 21.9 ft. – scribing visible (2012 BLM)
- 15" D. Fir bears N 55-3/4° E 16.3 ft. – scribing visible (2012 BLM)

Monument Detail

Sketch

Monument Set (Procedures and Description)

None

New Accessories

None

Location & Comments

Corner has steel post _____ Compass Declination 16° East

adjacent to it. _____ Firm/Agency Northwest Land

All BT's have red painted _____ Surveying Inc.

bands and yellow tags. _____ Address P.O. Box 2827
_____ Florence, OR 97439

_____ Party Chief Ron Rice

_____ Notes _____

_____ Witness _____

Surveyor's Seal



RENEWS: 12-31-2014

C.S. FILE 65/78-31