

OREGON CORNER RESTORATION FORM

Section 22 Township 20 South, Range 8 West
County Douglas Date 21 March 2013

FILED
Date: 5/6/2013 By: JC
This survey consists of:
Map: _____
Narrative: _____
Corner Rpt: CS65/78-33
DOUGLAS COUNTY
SURVEYOR

Corner Description

Section Corner
Sections 21,22,27,28

- Condition Report Only
- Not Found
- Renewed
- Unrecorded
- Surveyed In
- Referenced Out

Previous Renewals / Surveys, etc.

Monument (s) & Accessories Found: (Condition and Source)

Found 1950 GLO brass cap with the following accessories:

- A decayed hemlock snag, 14" dia., bears S.31° W., 53.5 ft., no marks visible.
(Found same)
- A cedar stump, 70" dia., bears N.83½° W., 46.2 ft., no marks visible on open blaze.
(Found same)
- A burned cedar snag, 44" dia., bears N.13° E., 115.5 ft., no marks visible.
(Found same)
- A fir, 20" dia., bears N.80½° E., 22.8 ft., mkd. T20S R8W S22 BT.
(Now 24", healed face)
- A fir, 21" dia., bears S.4½° E., 53.0 ft., mkd. T20S R8W S27 BT.
(Now 23", healed face)
- A fir, 23" dia., bears S.41° W., 56.2 ft., mkd. T20S R8W S28 BT.
(Now 26", healed face)
- A fir, 21" dia., bears N.31½° W., 109.9 ft., mkd. T20S R8W S21 BT.
(Now 24", healed face)

Monument Detail

Sketch

Monument Set (Procedures and Description)

None

New Accessories

None

Location & Comments

Corner has steel post Compass Declination 16° East
adjacent to it. Firm/Agency Northwest Land
All BT's have red painted Surveying Inc.
bands and yellow tags. Address P.O. Box 2827
_____ Florence, OR 97439
_____ Party Chief Ron Rice
_____ Notes _____
_____ Witness _____

Surveyor's Seal



RENEWS: 12-31-2014

C.S. FILE 65/78-33