

OREGON CORNER RESTORATION FORM

Section 22 Township 20 South, Range 8 West
County Douglas Date 21 March 2013

Corner Description

1/4 Corner
Sections 21,22

Previous Renewals / Surveys, etc.

Monument (s) & Accessories Found: (Condition and Source)

Found 1950 GLO brass cap with the following accessories:

A cedar, 26" dia., bears S.29³/₄° E., 17 lks., with scribe marks 1/4 S visible on partially healed blaze. (Found 26" stump, burned face)

A root hole, bears S.61¹/₂° W., 107 lks., with a down fir alongside, 40" dia. no marks remaining on burned blaze. (Not searched for)

A fir stump, 48" dia. bears S.62° W. 132 lks. mkd: 1/4 S21 BT (Now 48" burned, rotted stump, no marks)

Monument Detail

Sketch

Monument Set (Procedures and Description)

None

New Accessories

13" D. Fir bears S 18° W 7.1 ft. – blazed, scribed 1/4 S21 BT

12" D. Fir bears N 28° W 1.3 ft. – blazed, scribed 1/4 S21 BT

18" D. Fir bears N 70° E 9.8 ft. – blazed, scribed 1/4 S22 BT

15" D. Fir bears S 17° E 17.6 ft. – blazed, scribed 1/4 S22 BT

Location & Comments

Corner has steel post Compass Declination 16° East

adjacent to it. Firm/Agency Northwest Land

All BT's have red painted Surveying Inc.

bands and yellow tags. Address P.O. Box 2827
Florence, OR 97439

Party Chief Ron Rice

Notes _____

Witness _____

FILED

Date: 5/6/2013 By: XC

This survey consists of:

Map: _____

Narrative: _____

Corner Rpt: CS 65/78-34

DOUGLAS COUNTY
SURVEYOR

- Condition Report Only
- Not Found
- Renewed
- Unrecorded
- Surveyed In
- Referenced Out

Surveyor's Seal



RENEWS: 12-31-2014

C.S. FILE CS 65/78-34