

OREGON CORNER RESTORATION FORM

Section 22 Township 20 South, Range 8 West
County Douglas Date 21 March 2013

FILED
Date: 5/7/2013 By: JC
This survey consists of:

Map: _____

Narrative: _____
Corner Rpt: CS 65/78-36

DOUGLAS COUNTY
SURVEYOR

Corner Description

1/4 Corner
Sections 22,23

- Condition Report Only
- Not Found
- Renewed
- Unrecorded
- Surveyed In
- Referenced Out

Previous Renewals / Surveys, etc.

Monument (s) & Accessories Found: (Condition and Source)

Found 1950 GLO brass cap with the following accessories:

A decayed fir stump, 50" dia., bears S.66° W., 37.6 ft., with scribe marks 1/4 S22 BT visible on open blaze. (Found Same)

A root hole with cedar log alongside, 8" dia., bears S.86° E., 17.8 ft., no marks visible. (Found same)

A fir, 13" dia., bears S.48° E., 7.7 ft., mkd. 1/4 S23 BT. (Now 15", healed face)

A fir, 9" dia., bears S.20° W., 19.0 ft., mkd. 1/4 S22 BT. (Now 15", healed face)

Monument Detail

Sketch

Monument Set (Procedures and Description)

None

New Accessories

11" D. Fir bears N 24° W 19.5 ft. – blazed, scribed 1/4 S22 BT

7" D. Fir bears N 6° E 6.6 ft. – blazed, scribed 1/4 S23 BT

Location & Comments

Corner has steel post _____ Compass Declination 16° East
 adjacent to it. _____ Firm/Agency Northwest Land
All BT's have red painted _____ Surveying Inc.
bands and yellow tags. _____ Address P.O. Box 2827
 _____ Florence, OR 97439
 _____ Party Chief Ron Rice
 _____ Notes _____
 _____ Witness _____

Surveyor's Seal



RENEWS: 12-31-2014

C.S. FILE 65/78-36