

CORNER REPORT FORM

Section 10 Township 30S Range 8W  
Douglas County Date 5-8-13

CORNER DESIGNATION 40500

Condition Report only  
Not Found  
Renewed  
Unrecorded  
Surveyed In  
Referenced out

Previous Renewals/Surveys, etc:

DCSD RENEWAL Aug. 1958

Monument(s) & Accessories Found: (Condition and Source)

DCSD BRASS CAP (POOR CONDITION)

22" FIR S18 1/2 E 49 5/8 FT scribed S15 T30S RBW CSBT

Monument Detail

Sketch

DCSD BRASS CAP

FILED

Date: 5/10/2013 By: SC

This survey consists of:

Map: \_\_\_\_\_

Narrative: \_\_\_\_\_

Corner Rpt: CS 65/78-38

DOUGLAS COUNTY  
SURVEYOR

Monument Set (Procedures and Description)

New Accessories

A 1 1/2" W. FIR N6W 9 5/8 FT scribed S9 T30S RBW BT  
12" W. FIR S68W 30' FT scribed S16 T30S RBW BT  
10" W FIR S74E 20 1/2 FT scribed S15 T30S RBW BT

Location & Comments

CORNER IS ON  
TOP OF SMALL  
N-S RIDGE 100' ±  
SOUTH OF OLD RD

Compass Declination

Firm/Agency: i.e. Engineering, Inc.

Address: 809 SE Pine St.  
Roseburg, OR 97470

Party Chief: J. LEONARD

Notes:

Witness: N. FROM DAHL

Surveyor's Seal

REGISTERED  
PROFESSIONAL  
LAND SURVEYOR

OREGON  
JULY 14, 1978  
RONALD A. QUIMBY  
1654

C.S. File No 65/78-38

EXP 12-31-14