

OREGON CORNER RESTORATION FORM

Section 20 Township 23 South, Range 8 West  
County Douglas Date 25 April 2013

FILED  
Date: 5/13/2013 By: JC  
This survey consists of:  
Map: \_\_\_\_\_  
Narrative: \_\_\_\_\_  
Corner Rpt: CS 65/78-40

DOUGLAS COUNTY  
SURVEYOR

Corner Description

1/4 Corner  
Sections 20,21

- Condition Report Only
- Not Found
- Renewed
- Unrecorded
- Surveyed In
- Referenced Out

Previous Renewals / Surveys, etc.

Monument (s) & Accessories Found: (Condition and Source)

Found 2-1/2" brass cap, dated 1979, with stone adjacent and the following accessories:  
16" D. Fir bears S 82° W 7.4 ft. – healed face (Roberts 1979)  
19" D. Fir bears S 42° E 19.6 ft. – healed face (Roberts 1979)  
28" burned out stump bears N 12° E 39.3 ft.

Monument Detail

Sketch

Monument Set (Procedures and Description)

None

New Accessories

22" D. Fir bears S 2° W 31.5 ft. – blazed, scribed 1/4 S20 BT  
24" D. Fir bears N 16° E 20.5 ft. – blazed, scribed 1/4 S21 BT

Location & Comments

Corner has steel post \_\_\_\_\_ Compass Declination 16° East  
 adjacent to it. \_\_\_\_\_ Firm/Agency Northwest Land  
All BT's have red painted \_\_\_\_\_ Surveying Inc.  
bands and yellow tags. Address P.O. Box 2827  
 \_\_\_\_\_ Florence, OR 97439  
 \_\_\_\_\_ Party Chief Ron Rice  
 \_\_\_\_\_ Notes \_\_\_\_\_  
 \_\_\_\_\_ Witness \_\_\_\_\_

Surveyor's Seal



RENEWS: 12-31-2014

C.S. FILE 65/78-40