

FILED

OREGON CORNER RESTORATION FORM

Date: 5/13/2013 By: JC

This survey consists of:

Section 20 Township 23 South, Range 8 West
County Douglas Date 25 April 2013

Map: _____

Narrative: _____
Corner Rpt: CS 65/78-41

DOUGLAS COUNTY
SURVEYOR

Corner Description

S1/16 Corner
Sections 20,21

- Condition Report Only
- Not Found
- Renewed
- Unrecorded
- Surveyed In
- Referenced Out

Previous Renewals / Surveys, etc.

Monument (s) & Accessories Found: (Condition and Source)

Found 2-1/2" brass cap, dated 1979, with the following accessories:
20" D. Fir bears N 89° E 11.1 ft. – healed face (Roberts 1979)
15" D. Fir bears N 21° W 24.2 ft. – healed face (Roberts 1979)

Monument Detail

Sketch

Monument Set (Procedures and Description)

None

New Accessories

Location & Comments

Corner has steel post _____ Compass Declination 16° East
adjacent to it. _____ Firm/Agency Northwest Land
All BT's have red painted _____ Surveying Inc.
bands and yellow tags. _____ Address P.O. Box 2827
_____ Florence, OR 97439
_____ Party Chief Ron Rice
_____ Notes _____
_____ Witness _____

Surveyor's Seal



RENEWS: 12-31-2014

C.S. FILE 65/78-41