

OREGON CORNER RESTORATION FORM

Section 2 Township 28 South, Range 8 West  
County Douglas Date 3 June 2013

Corner Description

E1/16 Corner  
Section 2 only

Previous Renewals / Surveys, etc.

Monument (s) & Accessories Found: (Condition and Source)

Found 2-1/2" alum. cap, dated 2007, with the following accessories:

- 14" D. Fir bears N 53° W 8.2 ft. – healed face
- 19" D. Fir bears S 73° E 45.4 ft. – healed face

Monument Detail

Sketch

Monument Set (Procedures and Description)

None

New Accessories

Location & Comments

Corner has steel post \_\_\_\_\_ Compass Declination 16° East  
 adjacent to it. \_\_\_\_\_ Firm/Agency Northwest Land  
All BT's have red painted \_\_\_\_\_ Surveying Inc.  
bands and yellow tags. Address P.O. Box 2827  
 \_\_\_\_\_ Florence, OR 97439  
 \_\_\_\_\_ Party Chief Ron Rice  
 \_\_\_\_\_ Notes \_\_\_\_\_  
 \_\_\_\_\_ Witness \_\_\_\_\_

Surveyor's Seal



RENEWS: 12-31-2014

FILED  
 Date: 6/12/2013 By: JC  
 This survey consists of:  
 Map: \_\_\_\_\_  
 Narrative: \_\_\_\_\_  
 Corner Rpt: CS 65/78-47  
 DOUGLAS COUNTY  
 SURVEYOR