FILED
Date: 6/12/2013 By: JC
This survey consists of:
Map: _____
Narrative: _____
Corner Rpt: CS 65/78-48
DOUGLAS COUNTY SURVEYOR

OREGON CORNER RESTORATION FORM

Section 2 Township 28 South, Range 8 West
County Douglas Date 3 June 2013

Corner Description
1/4 Corner
Section 2 only

X Condition Report Only
___ Not Found
___ Renewed
___ Unrecorded
___ Surveyed In
___ Referenced Out

Previous Renewals / Surveys, etc.

Monument (s) & Accessories Found: (Condition and Source)

Found 2-1/2" alum. cap, dated 2007, with the following accessories:
8" D. Fir bears N 10° W 9.2 ft. – healed face
12" D. Fir bears N 18° E 16.7 ft. – healed face
12" D. Fir bears S 8° E 9.9 ft. – healed face
26" D. Fir bears S 28° E 22.2 ft. – scribing visible

Monument Detail

Sketch

Monument Set (Procedures and Description)
None

New Accessories

Location & Comments
Corner has steel post adjacent to it. All BT's have red painted bands and yellow tags.

Compass Declination 16° East
Firm/Agency Northwest Land Surveying Inc.
Address P.O. Box 2827
Florence, OR 97439
Party Chief Ron Rice
Notes _____
Witness _____

Surveyor's Seal

REGISTERED PROFESSIONAL LAND SURVEYOR
Ronald L. Rice
OREGON
JULY 9, 2002
RONALD L. RICE
54633LS

RENEWS: 12-31-2014

C.S. File 65/78-48