FILED
Date: 6-12-2013 By: JC
This survey consists of:
Map: _____
Narrative: _____
Corner Rpt: CS 65/78-49

DOUGLAS COUNTY
SURVEYOR

OREGON CORNER RESTORATION FORM

Section 2 Township 28 South, Range 8 West
County Douglas Date 3 June 2013

Corner Description
Standard Corner
Sections 2 and 3 only

_X_ Condition Report Only
___ Not Found
___ Renewed
___ Unrecorded
___ Surveyed In
___ Referenced Out

Previous Renewals / Surveys, etc.

Monument (s) & Accessories Found: (Condition and Source)

Found 3-1/4" BLM brass cap, dated 1961, with the following accessories:
36" D. Fir bears S 84° W 15.1 ft. – healed face
16" Hem. stump bears N 11° E (record N 11° W) 17.1 ft. – healed face
16" Hem. bears N 88° W 75.2 ft. – healed face
34" R. Cedar bears S 15° E 49.5 – healed face

Monument Detail

Sketch

Monument Set (Procedures and Description)
None

New Accessories

Location & Comments
Corner has steel post adjacent to it. All BT's have red painted bands and yellow tags.

Compass Declination 16° East
Firm/Agency Northwest Land Surveying Inc.
Address P.O. Box 2827
Florence, OR 97439
Party Chief Ron Rice
Notes _____
Witness _____

Surveyor's Seal

REGISTERED
PROFESSIONAL
LAND SURVEYOR
Ronald L. Rice
OREGON
JULY 9, 2002
RONALD L. RICE
54633LS

RENEWS: 12-31-2014

C.S. File 65/78-49