

OREGON CORNER RESTORATION FORM

Section 2 Township 28 South, Range 8 West
County Douglas Date 3 June 2013

FILED
Date: 6/12/2013 By: JC
This survey consists of:
Map: _____
Narrative: _____
Corner Rpt: CS 65/78-51

DOUGLAS COUNTY
SURVEYOR

Corner Description

1/4 Corner
Sections 2 and 3

- Condition Report Only
- Not Found
- Renewed
- Unrecorded
- Surveyed In
- Referenced Out

Previous Renewals / Surveys, etc.

Monument (s) & Accessories Found: (Condition and Source)

Found 2-1/2" County Surveyor's brass cap, dated 1966, with the following accessories:
 30" D. Fir snag bears S 37° W 13.9 ft. – visible bark scribe
 36" D. Fir. rotted stump bears N 39° E 11.9 ft. – no marks
 14" Yew. bears N 25° E 61.6 ft. – rotted face
 12" Yew (record N 45° W) down
 13" D. Fir bears N 82° E 8.7 ft. – healed face
 18" D. Fir bears S 8° W 26.1 ft. – scribing visible

Monument Detail

Sketch

Monument Set (Procedures and Description)

None

New Accessories

Location & Comments

Corner has steel post adjacent to it. Compass Declination 16° East
All BT's have red painted bands and yellow tags. Firm/Agency Northwest Land Surveying Inc.
 Address P.O. Box 2827 Florence, OR 97439
 Party Chief Ron Rice
 Notes _____
 Witness _____

Surveyor's Seal



RENEWS: 12-31-2014

C.S. File 65/78-51