

OREGON CORNER RESTORATION FORM

Section 16 Township 19 South, Range 8 West

County Douglas

Date 10 September 2013

FILED

Date: 9/10/2013 By: JC

This survey consists of:

Map: _____

Narrative: _____

Corner Rpt: CS 65/80-3

DOUGLAS COUNTY SURVEYOR

Corner Description

Section Corner
Sections 16, 17, 20, 21

- Condition Report Only
- Not Found
- Renewed
- Unrecorded
- Surveyed In
- Referenced Out

Previous Renewals / Surveys, etc.

Monument (s) & Accessories Found: (Condition and Source)

Found 2-1/2" GLO brass cap, dated 1952, with the following accessories:

- Fir, 32" dia., bears S.84°W., 29 lks., with an old blaze on E. face.
(Down, rotted)
- Fir, 42" dia., bears N.64°W., 23 lks., with an old blaze on NE face.
(Found 60" Fir with healed face)
- Fir, 48" dia., bears N.32°E., 91 lks., mkd: T19S R8W S16 BT.
(Found 69" Fir with healed face)
- Alder, 14" dia., bears S.73°45'E., 57 lks., mkd: T19S R8W S21 BT.
(Found 19" Alder with rotted face)

Monument Detail

Sketch

Monument Set (Procedures and Description)

None

New Accessories

None

Location & Comments

Corner has steel post _____ Compass Declination 16° East

adjacent to it. _____ Firm/Agency Northwest Land

All live BT's have red painted _____ Surveying Inc.

bands and yellow tags. _____ Address P.O. Box 2827
_____ Florence, OR 97439

_____ Party Chief Ron Rice

_____ Notes _____

_____ Witness _____

Surveyor's Seal



RENEWS: 12-31-2014