

OREGON CORNER RESTORATION FORM

FILED
Date: 9/10/2013 By: JC
This survey consists of:
Map: _____
Narrative: _____
Corner Rpt: CS 65/80-6

Section 16 Township 19 South, Range 8 West
County Douglas Date 10 September 2013

DOUGLAS COUNTY
SURVEYOR

Corner Description

1/4 Corner
Sections 16, 21

- Condition Report Only
- Not Found
- Renewed
- Unrecorded
- Surveyed In
- Referenced Out

Previous Renewals / Surveys, etc.

Monument (s) & Accessories Found: (Condition and Source)

Found 2-1/2" GLO brass cap, dated 1952, with the following accessories:

- Fir, 55" dia., bears N.10°E., 31 lks., with old blaze on SW face.
(Found root wad)
- Fir, 37" dia., bears S.19½°W., 58 lks., with old blaze on NE face.
(Found 50" Fir with healed face)
- Fir, 33" dia., bears N.81°E., 22 lks., mkd: 1/4 S16 BT.
(Found 56" Fir with healed face)
- Fir, 40" dia., bears S.42½°W., 74 lks., mkd: 1/4 S21 BT.
(Found 55" Fir with healed face)
- (Found unrecorded 12" Hemlock bearing S 12° W 14.2 ft. with healed face tagged 1991 BLM)

Monument Detail

Sketch

Monument Set (Procedures and Description)

None

New Accessories

11" D. Fir bears N 17° W 3.7 ft. – blazed, scribed 1/4 S16 BT

Location & Comments

Corner has steel post _____ Compass Declination 16° East
adjacent to it. _____ Firm/Agency Northwest Land
All live BT's have red painted _____ Surveying Inc.
bands and yellow tags. _____ Address P.O. Box 2827
 _____ Florence, OR 97439
 _____ Party Chief Ron Rice
 _____ Notes _____
 _____ Witness _____

Surveyor's Seal



RENEWS: 12-31-2014

340400

C.S. FILE 65/80-6