

CORNER REPORT FORM

Section 2 Township 32S Range 8W  
Douglas County Date 9-2013

CORNER DESIGNATION

W 1/4 35  
2

Condition Report only

Not Found  
Renewed  
Unrecorded  
Surveyed In  
Referenced out

Previous Renewals/Surveys, etc:

M 83-26

Monument(s) & Accessories Found: (Condition and Source)

Fd 1977 BLM BRASS CAP  
12" FIR N26W 828 FT (M 83-26 S26E)  
14" FIR S47W 475 FT (M 83-26 N47E)  
Both Trees BURNED  
Retaged

Monument Detail

Sketch

FILED

Date: 10-16-2013 By: SC  
This survey consists of:  
Map: \_\_\_\_\_  
Narrative: \_\_\_\_\_  
Corner Rpt: CS 65/80-14

DOUGLAS COUNTY  
SURVEYOR

Monument Set (Procedures and Description)

New Accessories

Set Alum post 2' East & 2' West.

Location & Comments

AREA BURNED  
7/2013

Surveyor's Seal



Compass Declination 15 1/2  
Firm/Agency: i.e. Engineering, Inc.

Address: 809 SE Pine St.  
Roseburg, OR 97470

Party Chief: J. LEONARD

Notes:

Witness: N FROINDHIL



Exp 12-31-14

C.S. File No 65/80-14