

CORNER REPORT FORM

Section 2 Township 32S Range BW  
Douglas County Date 9-2013

CORNER DESIGNATION

C.E 1/16

Condition Report only  
Not Found  
Renewed  
Unrecorded  
Surveyed In  
Referenced out

Previous Renewals/Surveys, etc:

M 83-26

Monument(s) & Accessories Found: (Condition and Source)

Ed 5/8" T. ROD & ALUMI CAP  
12" MADRONA N20E 23<sup>0</sup> FT (8' stub)  
8" MADRONA S33W 20<sup>3</sup> FT

Monument Detail

Sketch

FILED

Date: 10-16-2013 By: SC  
This survey consists of:  
Map: \_\_\_\_\_  
Narrative: \_\_\_\_\_  
Corner rpt. CS 65/80-17

DOUGLAS COUNTY  
SURVEYOR

Monument Set (Procedures and Description)

New Accessories

set Alum. post 2' North & 2' west  
Re TAG TREES

Location & Comments

Surveyor's Seal

Compass Declination 15 1/2  
Firm/Agency: i.e. Engineering, Inc.

Address: 809 SE Pine St.  
Roseburg, OR 97470

Party Chief: J. LEONARD

Notes:

Witness: N. Fronidah

REGISTERED  
PROFESSIONAL  
LAND SURVEYOR

OREGON  
JULY 14, 1978  
RONALD A. GUIN...  
1654

C.S. File No 65/80-17

EXP - 12-31-14

540640