

FILED

OREGON CORNER RESTORATION FORM

Date: 10-18-2013 By: SR

This survey consists of:

Map: _____

Narrative: _____

Corner Rpt: CS 65/80-21

Section 24 Township 20 South, Range 8 West
County Douglas Date 18 October 2013

DOUGLAS COUNTY
SURVEYOR

Corner Description

1/4 Corner
Sections 13, 24

- Condition Report Only
- Not Found
- Renewed
- Unrecorded
- Surveyed In
- Referenced Out

Previous Renewals / Surveys, etc.

Monument (s) & Accessories Found: (Condition and Source)

Found 2-1/2" GLO brass cap, dated 1954, with the following accessories:

Cedar, 33" dia., bears N.66°E., 76 lks., with fragmentary scribe marks visible on partially healed & burned blaze. Rescribed 1/4 S13 BT on new blaze.
(Found 33" Cedar stump, no scribing visible)

Cedar, 28" dia., bears S.36¼°E., 46 lks., with fragmentary scribe marks visible on partially healed & burned blaze. Rescribed 1/4 S24 BT on new blaze.
(Found 31" Cedar stump, no scribing visible)

Monument Detail

Sketch

Monument Set (Procedures and Description)

None

New Accessories

- 19" D. Fir bears N 64° W 4.2 ft. – blazed, scribed 1/4 S13 BT
- 24" D. Fir bears N 81° E 22.4 ft. – blazed, scribed 1/4 S13 BT
- 18" D. Fir bears S 74° E 14.6 ft. – blazed, scribed 1/4 S24 BT
- 16" D. Fir bears S 70° W 14.8 ft. – blazed, scribed 1/4 S24 BT

Location & Comments

Corner has steel post _____ Compass Declination 16° East
 adjacent to it. _____ Firm/Agency Northwest Land
All live BT's have red painted _____ Surveying Inc.
bands and yellow tags. _____ Address P.O. Box 2827
 _____ Florence, OR 97439
 _____ Party Chief Ron Rice
 _____ Notes _____
 _____ Witness _____

Surveyor's Seal



RENEWS: 12-31-2014