

FILED

Date: 10-18-2013 By: JC

This survey consists of:

Map: _____

Narrative: _____

Corner Rpt: CS 65/80-23

DOUGLAS COUNTY
SURVEYOR

OREGON CORNER RESTORATION FORM

Section 24 Township 20 South, Range 8 West
County Douglas Date 18 October 2013

Corner Description

E1/4 Corner
Section 24 only

- Condition Report Only
- Not Found
- Renewed
- Unrecorded
- Surveyed In
- Referenced Out

Previous Renewals / Surveys, etc.

Monument (s) & Accessories Found: (Condition and Source)

Found 2-1/2" GLO brass cap, dated 1954, with the following accessories:

- Decayed cedar stump, 39" dia., bears N.62°E., 15.8 ft., with no marks visible on partially healed blaze. (Found same)
- Root hole with uprooted burned cedar log, 20" dia., bears S.53°W., 7.9 ft., no marks visible. (Found same)
- Fir snag, 56" dia., bears N.7°W., 48.8 ft., with scribe marks 1/4 visible on open blaze. (Found same)
- Fir, 8" dia., bears N.78°W., 7.7 ft., mkd. X BT. (Found 10" fir with healed face)
- Fir, 16" dia., bears N.9 1/2°W., 33.6 ft., mkd. 1/4 S24 BT. (Found 18" fir with healed face)
- (Found 16" D. Fir bearing N 42° E 20.3 ft. with healed face. Appears to be 2005 BLM unrecorded bearing tree.)

Monument Detail

Sketch

Monument Set (Procedures and Description)

None

New Accessories

None

Location & Comments

Corner has steel post _____ Compass Declination 16° East
 adjacent to it. _____ Firm/Agency Northwest Land
All live BT's have red painted _____ Surveying Inc.
bands and yellow tags. _____ Address P.O. Box 2827
 _____ Florence, OR 97439
 _____ Party Chief Ron Rice
 _____ Notes _____
 _____ Witness _____

Surveyor's Seal



RENEWS: 12-31-2014

700340 - T20-8
100322 - T20-7

C.S. FILE 65/80-23