

OREGON CORNER RESTORATION FORM

FILED

Date: 10-18-2013 By: JC

This survey consists of:

Map: _____

Narrative: _____

Corner Rpt: CS 65/80-24

DOUGLAS COUNTY
SURVEYOR

Section 24 Township 20 South, Range 8 West

County Douglas

Date 18 October 2013

Corner Description

Section Corner

Sections 13, 24 only

___ Condition Report Only

___ Not Found

X Renewed

___ Unrecorded

___ Surveyed In

___ Referenced Out

Previous Renewals / Surveys, etc.

Monument (s) & Accessories Found: (Condition and Source)

Found 2-1/2" GLO brass cap, dated 1954, with the following accessories:

Maple stump 24" dia., bears N.70°E., 36 lks. dist., no marks remaining on burned blaze. (Missing)

Burned Fir stump 30" dia., bears S.65°W., 31 lks. dist., no marks remaining on burned blaze. (Found same)

Decayed Fir stump 36" dia., bears N.41°W., 63 lks. dist., no marks remaining. (Missing)

Sawed Fir stump 33" dia., bears N.27°W., 93 lks. dist. mkd. T20S R8W S13 BT. (Found same)

Sandstone outcrop 3x6x3 ft. above ground bears S 19-1/2° W, 62-1/2 lks. dist. mkd. X (Not recovered)

Monument Detail

Sketch

Monument Set (Procedures and Description)

None

New Accessories

19" D. Fir bears N 22° W 17.3 ft. – blazed, scribed T20S R8W S13 BT

19" D. Fir bears S 68° W 16.6 ft. – blazed, scribed T20S R8W S24 BT

Location & Comments

Surveyor's Seal

Corner has steel post ___ Compass Declination 16° East

adjacent to it. ___ Firm/Agency Northwest Land

All live BT's have red painted ___ Surveying Inc.

bands and yellow tags. ___ Address P.O. Box 2827

___ Florence, OR 97439

___ Party Chief Ron Rice

___ Notes _____

___ Witness _____

REGISTERED
PROFESSIONAL
LAND SURVEYOR

Ronald L. Rice

OREGON
JULY 9, 2002
RONALD L. RICE
54633LS

RENEWS: 12-31-2014

700400 T20-8
100302 T20-7

C.S. FILE

65/80-24