

CORNER REPORT FORM

Section 22 Township 32S Range 8W
Douglas County Date 11-2013

CORNER DESIGNATION

440400

Condition Report only
Not Found
Renewed
Unrecorded
Surveyed In
Referenced out

Previous Renewals/Surveys, etc:

DCSO 1968 CS 54/65
MARK SMALLEY 1996 CS 65/15-7A

Monument(s) & Accessories Found: (Condition and Source)

Fd DCSO I.P. PE & BRASS CAP
A 10" TAN OAK N 30 W 40.1 FT Vis. Scribes
A 39" FIR S 30 W 39.0 FT HEALED FACE
A 14" FIR S 71 W 18.9 FT HEALED FACE
A 10" FIR N 44 W 23.8 " "

Monument Detail

Sketch

COUNTY SURVEYORS OFFICE
T32S R8W
1/4 515
522
1968

FILED
Date: 11/12/2013 By: DC
This survey consists of:
Map: _____
Narrative: _____
Corner Rpt: CS 65/80-40

DOUGLAS COUNTY
SURVEYOR

Monument Set (Procedures and Description)

New Accessories

set Alum Post 2' EAST
Retag BEARING Trees

Location & Comments

AREA BURNED
8-2013

Compass Declination 15
Firm/Agency: i.e. Engineering, Inc.

Address: 809 SE Pine St.
Roseburg, OR 97470

Party Chief: J. LEONARD

Notes:

Witness: N. Fromdahl

Surveyor's Seal

REGISTERED
PROFESSIONAL
LAND SURVEYOR

OREGON
JULY 14, 1978
RONALD A. QUIMBY
1634

EXP 12-31-14

C.S. File No 65/80-40