

CORNER REPORT FORM

Section 1 Township 32 Range 8
Douglas County Date 11-2013

CORNER DESIGNATION

640600

Condition Report only

- Not Found
- Renewed
- Unrecorded
- Surveyed In
- Referenced out

Previous Renewals/Surveys, etc:

BLM Survey July 1975 DCSO RECORDS Vol. 40 P15980
M 83-25 (1980) M 164-73 (2013)

Monument(s) & Accessories Found: (Condition and Source)

FD BLM BRASS CAP
A 12" LIVE OAK N10°E 17¹/₂ FT Vis. Scribe
A 16" fir S56E 37³/₄ FT " "

Monument Detail

Sketch

U.S. Department of Interior
CADASTRAL Survey
T32S R8W
1/4 S1
S12
1975

FILED
Date: 11/13/2013 By: SC
This survey consists of:
Map: _____
Narrative: _____
Corner Rpt: CS 65/8043

Monument Set (Procedures and Description)

DOUGLAS COUNTY
SURVEYOR

New Accessories

RETAG TREES

Location & Comments

COR IS APPROX
150' EAST OF
RAILROAD
AREA BURNED
7-2013

Compass Declination 15
Firm/Agency: i.e. Engineering, Inc.

Address: 809 SE Pine St.
Roseburg, OR 97470

Party Chief: J. LEONARD

Notes:

Witness: N. Frowdahl

Surveyor's Seal

REGISTERED
PROFESSIONAL
LAND SURVEYOR

OREGON
JULY 14, 1978
RONALD A. QUIMBY
1654

C.S. File No 65/80-43

EXP 12-31-14