


CORNER RECORD (SEARCH)

Index File No. R-10.2 Tract or Survey No. _____ Cor. No. _____

T 29S R 1W R.D. TILLER County DOUGLAS

Merid. Willamette N.F. UMPQUA State OR

Corner Diagram



DESCRIBE CORNER MONUMENT FOUND

A 2 1/2 INCH BRASS CAP ON A 2 1/2 INCH IRON PIPE PROJECTING 9 INCHES IN A MOUND OF STONE
GOOD CONDITION

DESCRIBE BEARING TREES OR OTHER OFFICIAL ACCESSORIES FOUND

A 24 IN. FIR BRS. N 61 1/2° E 57.5 FT. DIST WITH A HDB
A 8 IN. CHINQUAPIN BRS. S 19° E 71.5 FT. DIST. WITH 1/64S28 VISIBLE ON UPPER FACE AND A ROTTEN LOWER FACE

PHOTO I.D. DATA

Photo No. _____
Filed At _____
Object Ident _____
Ident By _____

Signature

PLANE COORDINATE POSITION DATA

State _____ Zone _____
X _____
Y _____
Estab. By _____
Agency _____

DESCRIBE CORNR LOCATION RELATIVE TO NEAR-BY FEATURES, ALSO HOW TO REACH CORNER

CORNER LIES ON A GENTLE NORTH SLOPE APROXIMATLY 2000 FT. WEST OF ROAD 2827-013

Signature

LANCE GOUCHER

Title

Survey Tech.

Division

Headquarters

Medford

Date

6/2012

FS-7100-52 (3/68)

CORNER RECORD (PERPETUATION)

MONUMENT: DESCRIBE NEW MONUMENT SET, OR WORK DONE TO PRESERVE EXISTING MONUMENT

PAINTED BT'S AND NAILED SIGNS AS NEEDED

ACCESSORIES: DESCRIBE NEW BT'S, WITNESS OBJECTS, ETC. ESTABLISHED, OR WORK DONE TO PRESERVE EXISTING EVIDENCE
MARKED A NEW BT:

A 13 IN. FIR BRS S 83 1/2° E 6.5 FT DIST. MARKED EW1/64S28BT ON A DOUBLE BLAZE WITH A BRASS WASHER STAMPED LS 2561 NAILED TO LOWER BLAZE

FILED

Date: 11/18/2013 By: JC

This survey consists of:

Map: _____

Corner Rpt. CS 65/80-48

**DOUGLAS COUNTY
SURVEYOR**

REGISTERED
PROFESSIONAL
LAND SURVEYOR

John Ransom

OREGON
JULY 21 1992
JOHN C. RANSOM
2561

C.S. File No 65/80-48