

Index
File No. U-8

CORNER RECORD (SEARCH)


Tract or
Survey No.

Cor.
No.

T 29S R 1W R.D. TILLER County DOUGLAS

Merid. Willamette N.F. UMPQUA State OR

Corner Diagram



DESCRIBE CORNER MONUMENT FOUND

A 3 1/2 INCH BRASS CAP ON A 2 1/2 IN IRON PIPE PROJECTING 3 INCHES ABOVE GROUND IN GOOD CONDITION.

DESCRIBE BEARING TREES OR OTHER OFFICIAL ACCESSORIES FOUND

A 10 IN I CEDAR BRS. WEST 18.3 FT. DIST. WITH A HB

A ROOT HOLE WITH A 20 IN. WIND BLOWN FIR ALONG SIDE BRS. S 55 1/2° E 25.8 FT. DIST. WITH A HB

PHOTO I.D. DATA

Photo No.
Filed At
Object Ident
Ident By
Signature

DESCRIBE CORNER LOCATION RELATIVE TO NEAR-BY FEATURES, ALSO HOW TO REACH CORNER

PLANE COORDINATE
POSITION DATA

CORNER LIES ON A GENTLE SLOPE 1400 FT. EAST OF RD. 2800.200 AT THE CORNER OF A PRIVATE CLEAR CUT

State | Zone
X
Y
Estab. By
Agency

Signature
LANCE GOUCHER

Title
Survey Tech.

Division

Headquarters
Medford

Date
5/2011

FS-7100-52 (3/68)

CORNER RECORD (PERPETUATION)

MONUMENT: DESCRIBE NEW MONUMENT SET, OR WORK DONE TO PRESERVE EXISTING MONUMENT

Painted bearing trees, nailed signs and tags and cleared brush around corner

ACCESSORIES: DESCRIBE NEW BT'S, WITNESS OBJECTS, ETC. ESTABLISHED, OR WORK DONE TO PRESERVE EXISTING EVIDENCE MARKED A NEW BT:

A 10 IN. FIR BRS N 6 1/4° E. 27.8 FT DIST. MARKED SE1/16S29BT ON A DOUBLE BLAZE WITH A WASHER STAMPED LS2561 ON THE LOWER FACE

FILED

Date: 11/18/2013 By: SC

This survey consists of:

Map _____

Narrative _____

Corner Rpt: CS 65/80-49

DOUGLAS COUNTY
SURVEYOR

REGISTERED
PROFESSIONAL
LAND SURVEYOR

John Ransom

OREGON
JULY 21, 1892
JOHN C. RANSOM
2561

C.S. File No 65/80-49