

Index File No. A-1 **CORNER RECORD (SEARCH)** Tract or Survey No. \_\_\_\_\_ Cor. No. \_\_\_\_\_

T 30S R 1W R.D. TILLER County DOUGLAS

Merid. Willamette N.F. UMPQUA State OR

Corner Diagram

PHOTO I.D. DATA

Photo No.
Filed At
Object Ident
Ident By
Signature

PLANE COORDINATE POSITION DATA

State	Zone
X	
Y	
Estab. By	
Agency	

DESCRIBE CORNER MONUMENT FOUND

A 4 INCH BRASS CAP ON A 3 INCH IRON PIPE PROJECTING 15 INCHES ABOVE GROUND IN GOOD CONDITION.

---

DESCRIBE BEARING TREES OR OTHER OFFICIAL ACCESSORIES FOUND

A 18 IN. FIR BRS. N44° W 26.8 FT. DIST WITH A HB  
 A 17 IN. FIR SNAG BRS. N 73° E 17.5 FT. DIST WITH A HDB  
 A 12 IN. FIR BRS. S 20° E 38.4 FT. DIST. WITH A HDB ( RECORD S 25° E)  
 A 15 IN. FIR BRS. S41°W 33.0 FT DIST WITH A HDB  
 A ROTTEN FIR STUMP, SIZE INDETERMINANT BRS. S 10 1/2° E 13.0 FT. DIST. T30SR1WS6 VISIBLE ON OPEN FACE, SCRIBING VISIBLE ON PATIALY VISIBLE OLDER FACE (RECORD S 09° E)

---

DESCRIBE CORNER LOCATION RELATIVE TO NEAR-BY FEATURES, ALSO HOW TO REACH CORNER

CORNER LIES ON A GENTLE WEST SLOPE APROXIMATLY 250 FT. SOUTH OF THE END OF ROAD 2810-310

Signature	Title	Division	Headquarters	Date	FS-7100-52 (3/68)
<u>LANCE GOUCHER</u>	<u>Survey Tech.</u>		<u>Medford</u>	<u>5/ 2011</u>	

**CORNER RECORD (PERPETUATION)**

MONUMENT: DESCRIBE NEW MONUMENT SET, OR WORK DONE TO PRESERVE EXISTING MONUMENT

Painted bearing trees, nailed signs and tags and cleared brush around corner

ACCESSORIES: DESCRIBE NEW BT'S, WITNESS OBJECTS, ETC. ESTABLISHED, OR WORK DONE TO PRESERVE EXISTING EVIDENCE MARKED A NEW BT:

A 15 IN. FIR BRS. N 25 ° E. 23.9 FT DIST. MARKED T29SR1WS31BT ON A DOUBLE BLAZE WITH A WASHER STAMPED LS2561 ON THE LOWER FACE

**FILED**  
 Date: 11/18/2013 By: JC  
 This survey consists of:  
 Map: \_\_\_\_\_  
 Narrative: \_\_\_\_\_  
 Corner Rpt: CS 65/80-50

**DOUGLAS COUNTY SURVEYOR**

REGISTERED PROFESSIONAL LAND SURVEYOR  
John Ransom  
 OREGON  
 JULY 21 1982  
 JOHN C. RANSOM  
 2561

**C.S. File No** 65/80-50