

CORNER REPORT FORM

Section 24 Township 32S Range 8W

Douglas County

Date 11-2013

CORNER DESIGNATION

600340

Condition Report only

- Not Found
- Renewed
- Unrecorded
- Surveyed In
- Referenced out

Previous Renewals/Surveys, etc:

DCSO 1968

Monument(s) & Accessories Found: (Condition and Source)

County Surveyors Office

BRASS CAP

A 18" FIR N51E 30° FT (REC 551E) GOOD SCAR

A 29" FIR N76W 39° FT GOOD SCAR

A 28" FIR S62W 64°

Monument Detail

Sketch

County Surveyors Office

1/4 23/24  
1968

FILED

Date: 11/25/2013 By: X

This survey consists of:

Map: \_\_\_\_\_

Narrative: \_\_\_\_\_

Corner Rpt: C565/80-56

Monument Set (Procedures and Description)

DOUGLAS COUNTY  
SURVEYOR

New Accessories

Location & Comments

CORNER IS  
APPROX 150' west  
OF ROAD  
AREA BURNT  
7-2013

Compass Declination 15°

Firm/Agency: i.e. Engineering, Inc.


Address: 809 SE Pine St.  
Roseburg, OR 97470

Party Chief: J. Leonard

Notes:

Witness: N. Fromdahl

Surveyor's Seal



Ronald A. Quimby  
OREGON  
JULY 14, 1978  
RONALD A. QUIMBY  
1634

EXP 12-31-14

C.S. File No 65/80-56