

CORNER REPORT FORM

FILED

Section 28
Douglas County
PLSS Number
340240

Township 31S Range 8W
Date 12-2013

Date: 12/19/2013 By: SC
This survey consists of:
Map: _____

Narrative: _____
Corner Rpt: CS 65/80-64
DOUGLAS COUNTY
SURVEYOR

CORNER DESIGNATION

C 1/4 Sec. 28

- Condition report only
- Not Found
- Renewed
- Unrecorded
- Surveyed In
- Referenced out

Previous Renewals/Surveys, etc:

M 87-74
LS 2354 CS 43/154-4


Monument(s) & Accessories Found: (Condition and Source)

Fd 5/8" I. Rod with Alum CAP
A 21" fir N 130E 22 FT PARTIALLY HEALED SCAR
A 14" fir S 149, S 33E 14 FT OPEN SCAR
Both Trees badly burnt No Tree's available

Monument Detail

Alum CAP

Sketch



Monument Set (Procedures and Description)

New Accessories

Surveyor's Seal

Location & Comments

Alum Post 6'
North.
AREA burnt
8/2013

Compass Declination 15°
Firm/Agency: 1e engineering
Address: 809 S.E. Pine
Roseburg
Party Chief: J. LEONARD
Notes:
Witness: N From Dahl

REGISTERED
PROFESSIONAL
LAND SURVEYOR

OREGON
JULY 14, 1978
DONALD A. QUIMBY
1654

C.S. File EXP 12-31-14
CS 65/80-64