

FILED

OREGON CORNER RESTORATION FORM

Date: 1-13-2014 By: JC
This survey consists of:
Map: _____
Narrative: _____
Corner Rpt: CS 65/82-9

Section 12 Township 20 South, Range 8 West
County Douglas Date 8 January 2014

DOUGLAS COUNTY
SURVEYOR

Corner Description

CW1/16 Corner
Section 12

- Condition Report Only
- Not Found
- Renewed
- Unrecorded
- Surveyed In
- Referenced Out

Previous Renewals / Surveys, etc.

Monument (s) & Accessories Found: (Condition and Source)

Found 3" Aluminum Cap dated 1986 County Survey File M 103-63
12" D. Fir bears N 79° W 103.7' – healed face
18" D. Fir bears N 33° E 30.9' – healed face

Monument Detail

Sketch

Monument Set (Procedures and Description)

None

New Accessories

None

Location & Comments

Corner has alum. post _____ Compass Declination 16° East
 adjacent to it. _____ Firm/Agency Northwest Land
All live BT's have red painted _____ Surveying Inc.
bands and yellow tags. _____ Address P.O. Box 2827
 _____ Florence, OR 97439
 _____ Party Chief Ron Rice
 _____ Notes _____
 _____ Witness _____

Surveyor's Seal



RENEWS: 12-31-2014

620540

C.S. FILE 65/82-9