

OREGON CORNER RESTORATION FORM

Section 12 Township 19 South, Range 9 West
County Douglas Date 11 June 2014

Corner Description

1/4 Corner
Sections 1, 12

Previous Renewals / Surveys, etc.

Monument (s) & Accessories Found: (Condition and Source)

Found 2-1/2" GLO brass cap, dated 1957, with the following accessories:
39" D. Fir bears N 16-1/2° W 9.2' – healed face
28" D. Fir snag bears S 51° E 43.6' – healed face

Monument Detail

Sketch

Monument Set (Procedures and Description)

None

New Accessories

45" D. Fir bears N 81-1/2° E 45.1' – blazed, scribed 1/4 S1 BT

Location & Comments

Corner has steel post _____ Compass Declination 16° East
adjacent to it. Firm/Agency Northwest Land
All live BT's have red painted Surveying Inc.
bands and yellow tags. Address P.O. Box 2827
_____ Florence, OR 97439
_____ Party Chief Ron Rice
_____ Notes _____
_____ Witness _____

FILED

Date: 6/30/2014 By: JC

This survey consists of:

Map: _____

Narrative: _____

Corner Rpt: CS 65/82-48

DOUGLAS COUNTY
SURVEYOR

- ___ Condition Report Only
- ___ Not Found
- X Renewed
- ___ Unrecorded
- ___ Surveyed In
- ___ Referenced Out

Surveyor's Seal



RENEWS: 12-31-2014

C.S. FILE 65/82-48