

FILED

Date: 8-7-2014 By: JC

This survey consists of:

Map: _____

Narrative: _____

Corner Rpt: C.S. 65/86-5

DOUGLAS COUNTY
SURVEYOR

CORNER REPORT FORM

Section 14 Township 30 S Range 8 W
Douglas County Date 7/28/14
PLSS Number 500440

CORNER DESIGNATION

West 1/4 corner

- Condition Report only
- Not Found
- Renewed
- Unrecorded
- Surveyed In
- Referenced out

Previous Renewals/Surveys, etc:

Original by Byars in 1882.
Set by proportion by B.L.M. in 1964.

Monument(s) & Accessories Found: (Condition and Source)

Found standard B.L.M. brass cap from 1964.
A 36" diam. Fir stump w/healed blaze bears N.44°E., 33.7 feet.
The 1964 BT to the NW is gone.

Monument Detail

Sketch

Standard B.L.M. brass cap

Monument Set (Procedures and Description)

N/A


New Accessories

A 9" diam. Fir scribed "1/4 S14 BT" bears S.27°E., 17.3 feet.
An 11" diam. Madrone scribed "1/4 S15 BT" bears S.84°W., 4.1 feet.
A 6 foot steel post is set 2 feet North 1° West


Surveyor's Seal

Location & Comments

Compass Declination 15 1/2 E
Firm/Agency: David Edwards Land Surveying
Address: P.O. Box 361
Oakland, Oregon 97462
Party Chief: Brant Miller
Notes: _____
Witness: Eric Sprinkle



David A. Edwards



Renews 12/31/15

C.S. File 65/86-5