

CORNER REPORT FORM

FILED

Section 35 Township 32S Range 7W  
Douglas County Date 8/20/14  
PLSS Number 600140

Date: 8-26-2014 By: JC  
This survey consists of:  
Map: \_\_\_\_\_  
Narrative: \_\_\_\_\_  
Corner Rpt: CS 65/86-12  
DOUGLAS COUNTY  
SURVEYOR

CORNER DESIGNATION

1/4 COR 35/36

- Condition report only
- Not Found
- Renewed
- Unrecorded
- Surveyed In
- Referenced out

Previous Renewals/Surveys, etc:

RONALD BRANDT MB3-29  
BLM RESURVEY 2002

Monument(s) & Accessories Found: (Condition and Source)

BRASS CAP & I.P. REMOVED FD MAGNET & PLASTIC (HASC.)  
 12" D. FIR N 20 1/2 EAST 30.2 FT GOOD SCAR  
 12" D FIR N 80 W 16.2 FT GOOD SCAR  
 1" IRON PIPE SB 9 W 2.9 FT  
 MADRONE STUMP EAST 0.1 FD (BADLY BURNED)  
 18" FIR STUMP S 36 W 18.2 FT " "  
 19" FIR STUMP S 85 1/2 E 35.3  
 17" FIR STUMP S 82 E 33.6  
 Monument Detail HEATED BLAZE Sketch

Monument Set (Procedures and Description)

A 5/8" x 30" I. ROD with yellow PLASTIC CAP  
set over MAGNET & RECORD DIST FROM BT'S &  
FD I. PIPE

New Accessories

3" MADRONE S 53 E 12 3/4 FT SCRIBED 1/4 S 36 BT.

Surveyor's Seal

Location & Comments

AREA BURNED IN  
AUG 2013  
CORNER LIES  
APPROX 40' NORTH  
OF ROAD

Compass Declination 15 1/2  
Firm/Agency: i.e. Engineering, Inc.  
Address: 809 SE Pine St., Roseburg, OR 97470

Party Chief: N. F. WOODHILL  
Notes:  
Witness: R. OLSEN

REGISTERED  
PROFESSIONAL  
LAND SURVEYOR

*Ronald A. Quiner*  
OREGON  
JULY 14, 1978  
RONALD A. QUINER  
1034  
EXP 12-31-14

C.S. File CS 65/86-12