

CORNER REPORT FORM

FILED

Section 4 Township 23S Range 7W
Douglas County Date 9/20/14
PLSS Number 35100-732-7
340700-733-7

Date: 9-17-2014 By: SC
This survey consists of:
Map: _____
Narrative: _____
Corner Rpt: CS 65/86-20
DOUGLAS COUNTY
SURVEYOR

CORNER DESIGNATION

1/4 COR S4 ONLY

- Condition report only
- Not Found
- Renewed
- Unrecorded
- Surveyed In
- Referenced out

Previous Renewals/Surveys, etc:

PRICE 1954 CS 41/301
DCSO 1967

Monument(s) & Accessories Found: (Condition and Source)

1 1/2" IRON PIPE
15" CHINGUAPIN S 71 1/2 E 14 1/2 FT HONLED SCAR
16" CHINGUAPIN S 0 1/2 E 26 FT " "

Monument Detail

Sketch

Monument Set (Procedures and Description)

New Accessories

Surveyor's Seal

Location & Comments

AREA BADLY
BURNED 2013

Compass Declination 15 1/2
Firm/Agency: i.e. Engineering, Inc.
Address: 809 SE Pine St., Roseburg, OR 97470

Party Chief: N. F. ONDAHL
Notes:
Witness: D. MAURING.

REGISTERED
PROFESSIONAL
LAND SURVEYOR

Ronald A. Gimby

OREGON
JULY 14, 1978
RONALD A. GIMBY
1634

EXP 12-31-14

C.S. File 65/86-20