

FILED
Date: 2/25/2015 By: SC
This survey consists of:
Map: _____
Narrative: _____
Corner Rpt: CS 65/87-4
DOUGLAS COUNTY
SURVEYOR

CORNER REPORT FORM

Section 34 Township 31 S Range 9 W
Douglas County Date 2/24/2015
PLSS Number 400200

CORNER DESIGNATION

NW corner of Section 34.

___ Condition Report only
___ Not Found
 Renewed
___ Unrecorded
___ Surveyed In
___ Referenced out

Previous Renewals/Surveys, etc:

Original by W.H. Byars in 1900. Renewed by D.C.S. in 1967.
B.L.M. dependent resurvey in 1973.

Monument(s) & Accessories Found: (Condition and Source)

Found 1967 D.C.S. brass cap in good condition.
Orig. 19" diam. Fir w/healed faces bears S.31°W., 16.5 feet.
1973 B.L.M. trees: 15" diam. Fir w/healed face bears S.27½°E., 65.3 feet.
12" diam. Fir stump bears N.17°W., 28.1 feet.

Monument Detail

Sketch

Standard D.C.S. brass capped iron pipe.

Monument Set (Procedures and Description)

N/A

New Accessories

A 12" diam. Fir scribed "T31S R9W S27 BT" bears N.32°E., 6.5 feet.
A six foot steel post is set 2 feet South.

Surveyor's Seal

Location & Comments



Compass Declination 15° East
Firm/Agency: David Edwards Land Surveying
Address: P.O. Box 361
Oakland, Oregon 97462
Party Chief: Brant Miller
Notes: _____
Witness: Eric Sprinkle

C.S. File 65/87-4