

CORNER REPORT FORM

FILED

Section 29
Douglas County
PLSS Number
240240

Township 32S Range 4W
Date 1-2015

Date: 2/26/2015 By: JC
This survey consists of:
Map: _____
Narrative: _____
Corner Rpt: CS 65/87-11
DOUGLAS COUNTY
SURVEYOR

CORNER DESIGNATION

C 1/4 529

- Condition report only
- Not Found
- Renewed
- Unrecorded
- Surveyed In
- Referenced out

Previous Renewals/Surveys, etc:

SET BY PRICE CS 41/375

Monument(s) & Accessories Found: (Condition and Source)

FD 1 1/2" I. PIPE
13" Forked MADRONE N 47E 33.7 FT VIS. SCAR
23" D. FIR 537°E 11.9 FT GOOD SCAR

Monument Detail

Sketch

Monument Set (Procedures and Description)

New Accessories

A 9" MADRONE N 25°E 14.2 FT Scribed C 1/4 529 BT
5" D. FIR N 5°W 18.5 FT Scribed C 1/4 529 BT

Surveyor's Seal

Location & Comments

CORNER IS ON TOP
OF ROAD CUT BANK
IN TIMBER CORNER

Compass Declination 15 1/2
Firm/Agency: i.e. Engineering, Inc.
Address: 809 SE Pine St., Roseburg, OR 97470

Party Chief: N. FROMMHAHL
Notes:
Witness: R. OLSEN

REGISTERED
PROFESSIONAL
LAND SURVEYOR

OREGON
JULY 14, 1978
RONALD A. QUIMBY
1054

EXP 12-31-16

C.S. File

CS 65/87-11