

FIRST RE-ESTABLISHMENT

Section Corner common to Sections 31 and 32, Twp. 29 South, Range 4 East, and Sections 5 and 6, Twp. 30 South, Range 4 East, W.M. V=19°

Found, the iron post, 28 ins. (71 cm.) below the asphalt road, with 2½ ins. (6.4 cm.) diam. brass cap marked as recorded in 1929. Directly above this monument I set a 1x12 ins. (2.5x30 cm.) G.I. pipe over a 5/8 x 16 ins. (1.6x41 cm.) iron pin. both slightly below the road surface, and a 2½ ins. 6.4 cm.) brass cap flush with the surface marked: Jackson County 1977

T29S

R4E

S31 S32

S6 S5

T30S

from which the original bearing trees were found as follows, measuring to center of tree at bottom of the single blaze:

White pine, 30 ins. (76 cm.) diam bears S7½°E, 75.7 ft. (23.07 M.) Record; S11½°E, 75.5 ft. (23.01 M.)

Hemlock 24 ins. (61 cm.) diam. brs. N59½°E, 74.7 ft. (22.77 M.). Record; N59½°E, 64.7 ft. (19.72 M.).

Both trees have scribing visible in partially healed blaze.

A k-tag on a 24 ins. (61 cm.) diam. fir which bears N14°E, 39.2 ft. (11.95 M.) reads: "GWK 1956, S15°W, 37.0 ft. to corner. 18" deep."

I marked the following trees "CS "BT" and took measurements to center of tree at the lower blaze:

White pine 17 ins. (43 cm.) diam. bears S68°W, 65.7 ft. (20.03 M.).

White fir, 20 ins. (51 cm.) diam., brs. N14½°W, 71.9 ft. (21.92 M.).

I also set four nail and shiner straddles at 2.00 ft. (0.61 M.) in approximate cardinal directions from the corner.

September 12, 1977

R.Roberts

E.Graham

Approved By: Ed McGinty

Co. Surveyor

FILED

Date: 4/7/2015 By: JC

This survey consists of:

Map: DOWN LOADED FROM JACKSON

Narrative: CO. WEBSITE 4/6/2015

Corner Rpt: CS 65/87-39

DOUGLAS COUNTY
SURVEYOR