

FILED

Date: 7-13-2015 By: JC

This survey consists of:

Map: _____

Narrative: _____

Corner Rpt: CS 65/89-9

OREGON CORNER RESTORATION FORM

Section 8 Township 20 South, Range 7 West

County Douglas

Date 17 June 2015

DOUGLAS COUNTY
SURVEYOR

Corner Description

1/4

Sections 7, 8

Condition Report Only

Not Found

Renewed

Unrecorded

Surveyed In

Referenced Out

Previous Renewals / Surveys, etc.

Monument (s) & Accessories Found: (Condition and Source)

Found 2-1/2" Aluminum Cap on 5/8" rebar with steel post adjacent, set in CS 65/79-3
12" D. Fir lightly burned stump bears S 46-1/2° E 6.1' – scribing visible BT tag nailed to face
14" D. Fir lightly burned stump bears S 20-1/4° W 26.5' – scribing visible BT tag nailed to face
12" D. Fir lightly burned stump bears N 20° W 8.8' – scribing visible BT tag nailed to face
16" D. Fir lightly burned stump bears N 70-1/2° E 15.3' – scribing visible BT tag nailed to face

Monument Detail

Sketch

Monument Set (Procedures and Description)

None

New Accessories

None

Location & Comments

_____ Compass Declination 16° East
_____ Firm/Agency Northwest Land
_____ Surveying Inc.
_____ Address P.O. Box 2827
_____ Florence, OR 97439
_____ Party Chief Ron Rice
_____ Notes _____
_____ Witness _____

Surveyor's Seal



RENEWS: 12-31-2016

C.S. FILE 65/89-9