

FILED

Date: 11-17-2015 By: X

This survey consists of:

Map: _____

Narrative: _____

Corner Rpt: CS 65/89-58

OREGON CORNER RESTORATION FORM

SECTION 6 & 7 TOWNSHIP 21 S. RANGE 11 W. W.M.

**DOUGLAS COUNTY
SURVEYOR**

Corner Designation


1/4 CORNER SECTIONS 6 & 7
GCDB/PLSS CORNER ID No. 140600

Previous Renewals / Surveys, etc.:

M78-76
CS FILE 65/37-22A

- Condition Report Only
- Not Found
- Renewed
- Unrecorded
- Surveyed in
- Referenced Out

Monument Detail Sketch



Monument Found or Set (Procedures and Description)

FOUND MONUMENT:

A 2 1/2" BRASS CAP ON 2 1/2" IRON PIPE MARKED "T21S R11W S6 S7 1979 PLS1091" PER M78-76.

FOUND BT'S:

A 20" FIR STUMP WITH HEALED FACE AND TAG BEARS N62°55'W 25.0'.

A ROTTEN ALDER BLOW DOWN WITH NO VISIBLE MARKS BEARS S30°59'E 19.6'.

New Accessories

NEW BT'S MARKED:

AN 8" FIR FACE SCRIBED "S1/4 S6 BT" WITH X-CHOP AND TAG BEARS N51°E 11.40' TO A SPIKE AT SIDE CENTER.

AN 8" FIR FACE SCRIBED "S1/4 S6 BT" WITH X-CHOP AND TAG BEARS N59°W 13.95' TO A SPIKE AT SIDE CENTER.

Locations & Comments

LAT. AND LONG. PER GARMEN ETREX HAND HELD GPS
N: 43°46'08.8" W: 124°03'20.1"

Compass Declination 18° EAST

Firm / Agency: Estabrook Land Surveying Inc.

Address: PO BOX 574, Lakeside, OR 97449

Party Chief: Jerry Estabrook

Notes:

Witness: Josh Maxwell & Pat Coy

DATE 9/26/15

Surveyors Seal



A handwritten signature in cursive script, appearing to read 'Jerry Lee Estabrook'.



EXPIRES 12/31/15

C.S. File No 65/85-58