

FILED

Date: 6/15/2016 By: DC

This survey consists of:

Map: _____

Narrative: _____

Corner Rpt: CS65/93-7

OREGON CORNER RESTORATION FORM

Section 19 Township 20 South, Range 8 West

County Douglas

Date 12 May 2016

DOUGLAS COUNTY
SURVEYOR

Corner Description

NW

Section 19

Condition Report Only

Not Found

Renewed

Unrecorded

Surveyed In

Referenced Out

Previous Renewals / Surveys, etc.

Monument (s) & Accessories Found: (Condition and Source)

Found -2 1/2" GLO brass cap on iron pipe, dated 1954

45" Burned decayed cedar stump bears N 47° W 42.9' - no marks

77" Burned decayed cedar stump bears N 4° E 18.5' - no marks

21" Burned decayed hemlock stump bears S 10° E 66.0' - no marks

13" X 5' Alder stump bears N 26° E 3.5' - bark scribe visible

13" X 5' D. Fir stump bears S 19-1/2° E 16.4' - burned face

Monument Detail

Sketch

Monument Set (Procedures and Description)

None

New Accessories

Corner falls in recent logged and burned unit.

Placed steel posts adjacent to corner north and south.

High stump bearing trees have red painted band and face, plus bearing tree tag.

Location & Comments

_____ Compass Declination 16° East

_____ Firm/Agency Northwest Land

_____ Surveying Inc.

_____ Address P.O. Box 2827

_____ Florence, OR 97439

_____ Party Chief Ron Rice

_____ Notes _____

_____ Witness _____

Surveyor's Seal



RENEWS: 12-31-2016

C.S. File No 65/93-7