

FILED

Date: 12-6-2016 By: JC

This survey consists of:

Map: \_\_\_\_\_

Narrative: \_\_\_\_\_

Corner Rpt: CS 65/93-59

DOUGLAS COUNTY  
SURVEYOR

CORNER REPORT FORM

Section 15 Township 25 S Range 3 W  
Douglas County Date 11/29/2016  
PLSS Number 440500

CORNER DESIGNATION

1/4 corner common to  
Sections 10 and 15.

- Condition Report only
- Not Found
- Renewed
- Unrecorded
- Surveyed In
- Referenced out

Previous Renewals/Surveys, etc:

Original G.L.O. in 1883. G.L.O. set proportioned corner in 1943.  
Douglas Co. Surveyor Renewed in 1966.

Monument(s) & Accessories Found: (Condition and Source)

Found 1943 G.L.O. brass capped iron pipe. Falls in a logged area.  
The only remaining evidence of accessories is a 19" diam./ 66" tall high stumped Cedar with healed double blazes bears S. 85° E., 4.8 feet.  
A steel fence post bears North 0.4 feet.  
All other previously noted accessories are destroyed due to logging operations.

Monument Detail

Sketch

Standard G.L.O. brass cap.

NOTE: Corner lies on a moderately steep NW slope about 175' below a dirt road.

Monument Set (Procedures and Description)

N/A

New Accessories

A 5/8" diam. x 30" long rebar with red plastic cap mkd. "D.A. EDWARDS-L.S. 2339"  
bears N. 41° E., 13.04 feet with 6 foot steel post alongside.

A 5/8" diam. x 30" long rebar with red plastic cap mkd. "D.A. EDWARDS-L.S. 2339"  
bears South 15.70 feet with 6 foot steel post alongside. Surveyor's Seal

Location & Comments

Compass Declination 15° E

Firm/Agency: David Edwards Land Surveying

Address: P.O. Box 361

Oakland, Oregon 97462

Party Chief: David Edwards

Notes: "

Witness: "



*David A. Edwards*



Renews 12/31/17

C.S. File 65/93-59