

FILED

Date: 6/27/2017 By: SC

This survey consists of:

Map: _____

Narrative: _____
Corner Rpt: CS65/95-36

CORNER REPORT FORM

Section 22 Township 25S Range 8W
Douglas County Date _____
PLSS Number 500300

DOUGLAS COUNTY
SURVEYOR

CORNER DESIGNATION

S 22/23
27 26

- Condition Report only
- Not Found
- Renewed
- Unrecorded
- Surveyed In
- Referenced out

Previous Renewals/Surveys, etc:

DCSO Nov 1962 CS File 49/88

BLM dependent Resurvey DCSO RECORDS BK 33 Pgs 13772

Monument(s) & Accessories Found: (Condition and Source)

BLM BRASS CAP Per PLS 500300

14" Hemlock (orig 5") S 44 1/4 E 34 3/4 FT GOOD SCAR
20" Hemlock (orig 8") S 66 3/4 W 37 FT GOOD SCAR
20" Hemlock (orig 8") N 56 W 42 FT GOOD SCAR
48" FIR (orig 37") N 24 3/4 E 44 1/2 FT GOOD SCAR

Monument Detail

Sketch

Monument Set (Procedures and Description)

New Accessories

Surveyor's Seal

Location & Comments

Compass Declination 15 1/2 E



Firm/Agency: i.e. Engineering, Inc.

Address: 809 SE Pine St., Roseburg, OR 97470

Party Chief: N. Fromdahl

Notes:

Witness: R. OLSEN



EXP 12-31-18

C.S. File 65/95-36