

FILED

Date: 1-18-2015 By: SC

This survey consists of:

Map: _____

Narrative: _____

Corner Rpt: CS65/95-57

DOUGLAS COUNTY
SURVEYOR

CORNER REPORT FORM

Section 36 Township 23 S Range 8 W
Douglas County Date 8/7/2017
PLSS Number 700140

CORNER DESIGNATION

East 1/4 corner

- Condition Report only
- Not Found
- Renewed
- Unrecorded
- Surveyed In
- Referenced out

Previous Renewals/Surveys, etc:

Original: 1855 G.L.O. survey by Hutchinson. D.C.S. renewal in 1956.
Found by Roberts in 1982. Found on B.L.M. resurvey in 1982.

Monument(s) & Accessories Found: (Condition and Source)

Found the 1956 D,C,S, brass capped iron pipe in good condition.

The only remaining bearing trees noted in the 1982 B.L.M. visit are as follows:

- A 15" diam. Fir snag with healed blaze bears S. 63 1/4° E., 11.2 feet.
- A 16" diam. Fir snag with healed blaze bears S. 51° E., 16.8 feet.

Monument Detail

Sketch

Standard D.C.S. brass capped iron pipe.

Monument Set (Procedures and Description)

N/A

New Accessories

- A 16" diam. Fir scribed 1/4 S 31 BT bears S. 79° E., 19.7 feet.
- A 15" diam. Fir scribed 1/4 S 36 BT bears S. 77° W., 12.3 feet.
- A six foot steel post is set 2 feet South.

Surveyor's Seal

Location & Comments

Compass Declination 15°
 Firm/Agency: David Edwards Land Surveying
 Address: P.O. Box 361
Oakland, Oregon 97462
 Party Chief: Brant Miller
 Notes: _____
 Witness: Eric Sprinkle



C.S. File 65/95-57