

FILED

Date: 7-11-2018 By: X

This survey consists of:

Map: _____

Narrative: _____

Corner Rpt: C565/101-7

DOUGLAS COUNTY
SURVEYOR

CORNER REPORT FORM

Section 8 Township 23 S Range 7W

Douglas County Date 5-8-2018

PLSS Number _____

CORNER DESIGNATION

South 1/16 Corner
to Sections 7 and 8.

- _____ Condition Report only
- _____ Not Found
- X Renewed
- _____ Unrecorded
- _____ Surveyed In
- _____ Referenced out

Previous Renewals/Surveys, etc:

Set on M 90-32.

Monument(s) & Accessories Found: (Condition and Source)

Found 2 1/2" diam. iron pipe with brass cap in good condition.
A 20" diam. Myrtle with healed blaze bears N 84° W, 32.0'
The 36" diam. Hemlock S 40° E is gone.

Monument Detail

N/A

Sketch

Monument Set (Procedures and Description)

N/A

New Accessories

A 7" diam. Myrtle scribed "S 1/16 S7 BT" bears S 7° W, 20.8'

A six foot steel post is set 2' N 88° E

Surveyor's Seal

Location & Comments

Compass Declination 15° East

Firm/Agency: David Edwards Land Surveying


Address: P.O. Box 361

Oakland, Oregon 97462

Party Chief: Brant Miller

Notes: _____

Witness: Eric Sprinkle



C.S. File 65/101-7