

FILED

Date: 7-18-2018 By: sc

This survey consists of:

Map: \_\_\_\_\_

Narrative: \_\_\_\_\_

Corner Rpt: CS 65/101-29

DOUGLAS COUNTY  
SURVEYOR

CORNER REPORT FORM

Section 28 Township 21S Range 7W  
Douglas County Date 4-2018  
PLSS Number 340200

CORNER DESIGNATION

1/4 COR 28  
33

- Condition Report only
- Not Found
- Renewed
- Unrecorded
- Surveyed In
- Referenced out

Previous Renewals/Surveys, etc:

BLM DEPENDENT RESURVEY 1964 10132 P1 13514-5  
" " " " 1986 10148 P9 18216-6

Monument(s) & Accessories Found: (Condition and Source)

BLM BEASS CAP  
18" W. FIR N54°E 9' FT GOOD SCAR  
18" FIR S38 1/4°E 22' FT GOOD SCAR

Monument Detail

Sketch

T21S R7W  
528  
533  
1964

Monument Set (Procedures and Description)

New Accessories

12" FIR S1°E 13' FT SCRIBED 1/4 533 BT  
15" FIR S42°W 16' FT SCRIBED 1/4 533 BT  
6" steel POST 13' EAST - 1' WEST 1' NORTH

Surveyor's Seal

Location & Comments

Compass Declination 15' 30" E  
Firm/Agency: i.e. Engineering, Inc.  
Address: 809 SE Pine St., Roseburg, OR 97470

Party Chief: M. Fromdahl  
Notes: R. Heichel  
Witness: R. VINCENT

REGISTERED  
PROFESSIONAL  
LAND SURVEYOR

Ronald A. Quimby  
OREGON  
JULY 14, 1978  
RONALD A. QUIMBY  
1634

EXP 12-31-18

C.S. File 65/101-29